



# BioLab

# 8EHQ-0196-13559

RECEIVED  
OPPT NCIC

96 JAN 16 AM 7:58

January 3, 1995

ATTN: TSCA 8(e) Coordinator  
Document Processing Center (7407)  
Office of Pollution Prevention & Toxics  
401 M Street, S.W.  
Washington, DC 20460

ORIGINAL

Contains No CBI

Dear TSCA Section 8(e) Coordinator:

Bio-Lab is submitting a Section 8(e) substantial risk notification concerning human exposure. The following incident was reported in the Rocky Mountain Poison Center (RMPC) Bi-Monthly Report for the time period November 16-30, 1995. The report was received at Bio-Lab on December 13, 1995. The product involved in the alleged incident is BioGuard Off the Wall Surface Cleaner whose hazardous components are:

<u>Hazardous Components</u>	<u>WT %</u>	<u>CAS #</u>
Ethoxylated Nonylphenol	36.7%	9016-45-9
Phosphoric Acid	3.9%	7664-38-2
Muriatic Acid	3.1%	7647-01-0
Hydroxyacetic Acid	1.4%	79-14-1
Phosphorus Pentoxide	1.3%	1314-56-3

Consumer called RMPC on 11/16/95 to report that they had used the product to clean an outside fountain and alleged lung discomfort, dizziness, and sweating due to inhalation of the product. The poison control center's assessment was that they doubted that the symptoms were related to exposure to the product and that the symptoms, in part, may be caused by hypoglycemia. A follow-up call by the poison control center approximately two hours later indicated that the symptoms were resolving. The MSDS warns the product is irritating to nose and throat; avoid breathing vapors. RMPC reference number for this incident is 02884335.

If you have any questions, please call me at (404) 378-1761 ext. 359.

Sincerely,

Mark Jernigan  
Federal Registration Manager




8EHQ-96-13559  
INIT 01/16/96

96 JAN 24 PM 3:27

RECEIVED  
OPPT NCIC

Best Available Copy



89960000039